



2 Year Prevent

Quote Number: 10929738

Version: 1

Prepared For: COUNTY OF VENTURA

Attn:

Rep: Michele Marvin

Email: michele.marvin@stryker.com

Phone Number:

GPO: Vizient

Service Rep: Quincy Jountti

Email: quincy.jountti@stryker.com

Quote Date: 06/24/2024

Expiration Date: 09/28/2024

Contract Start: 07/25/2024

Contract End: 07/25/2026

| Delivery Address | | Sold To - Shipping | | Bill To Account | |
|------------------|-----------------------|--------------------|-----------------------|-----------------|---|
| Name: | COUNTY OF VENTURA | Name: | COUNTY OF VENTURA | Name: | COUNTY OF VENTURA HEALTH CARE AGENCY |
| Account #: | 20005535 | Account #: | 20005535 | Account #: | 206614 |
| Address: | 800 S VICTORIA AVE | Address: | 800 S VICTORIA AVE | Address: | 800 S VICTORIA AVE BOX L4610 |
| | VENTURA | | VENTURA | | VENTURA |
| | California 93009-0001 | | California 93009-0001 | | California 93009-0003 |

ProCare Products:

| # | Product | Description | Qty | Disc % Off Contract | Sell Price | Total |
|------|------------------|---|-----|---------------------|------------|-------------|
| 1.0 | SURFACES-PROCARE | PROCARE-SVC-BED-SURFACES Parts, Labor, Travel Preventative Maintenance Batteries Service | 7 | 22.0% | \$1,213.68 | \$8,495.76 |
| 2.0 | SURFACES-PROCARE | PROCARE-SVC-BED-SURFACES Parts, Labor, Travel Preventative Maintenance Batteries Service | 5 | 22.0% | \$1,213.68 | \$6,068.40 |
| 3.0 | SURFACES-PROCARE | PROCARE-SVC-BED-SURFACES Parts, Labor, Travel Preventative Maintenance Batteries Service | 2 | 22.0% | \$1,213.68 | \$2,427.36 |
| 4.0 | SURFACES-PROCARE | PROCARE-SVC-BED-SURFACES Parts, Labor, Travel Preventative Maintenance Batteries Service | 57 | 22.0% | \$1,213.68 | \$69,179.76 |
| 5.0 | SURFACES-PROCARE | PROCARE-SVC-BED-SURFACES Parts, Labor, Travel Preventative Maintenance Batteries Service | 14 | 22.0% | \$1,213.68 | \$16,991.52 |
| 6.0 | MEDSURG-PROCARE | PROCARE-SVC-MEDSURG-BEDS Parts, Labor, Travel Preventative Maintenance Batteries Service | 24 | 22.0% | \$995.28 | \$23,886.72 |
| 7.0 | SURFACES-PROCARE | PROCARE-SVC-BED-SURFACES Parts, Labor, Travel Preventative Maintenance Batteries Service | 4 | 22.0% | \$1,213.68 | \$4,854.72 |
| 8.0 | ICU-BARI-PROCARE | PROCARE-SVC-ICU-BARI-LD-BEDS Parts, Labor, Travel Preventative Maintenance Batteries Service | 11 | 22.0% | \$2,336.88 | \$25,705.68 |
| 9.0 | SURFACES-PROCARE | PROCARE-SVC-BED-SURFACES Parts, Labor, Travel Preventative Maintenance Batteries Service | 27 | 22.0% | \$1,213.68 | \$32,769.36 |
| 10.0 | SURFACES-PROCARE | PROCARE-SVC-BED-SURFACES | 24 | 22.0% | \$1,213.68 | \$29,128.32 |



2 Year Prevent

Quote Number: 10929738

Version: 1

Prepared For: COUNTY OF VENTURA

Attn:

Rep: Michele Marvin

Email: michele.marvin@stryker.com

Phone Number:

GPO: Vizient

Quote Date: 06/24/2024

Expiration Date: 09/28/2024

Contract Start: 07/25/2024

Contract End: 07/25/2026

Service Rep: Quincy Jountti

Email: quincy.jountti@stryker.com

| # | Product | Description | Qty | Disc % Off Contract | Sell Price | Total |
|----------------|------------------|---|-----|---------------------|------------|--------------|
| | | Parts, Labor, Travel Preventative Maintenance Batteries Service | | | | |
| 11.0 | ICU-BARI-PROCARE | PROCARE-SVC-ICU-BARI-LD-BEDS Parts, Labor, Travel Preventative Maintenance Batteries Service | 31 | 22.0% | \$2,336.88 | \$72,443.28 |
| 12.0 | MEDSURG-PROCARE | PROCARE-SVC-MEDSURG-BEDS Parts, Labor, Travel Preventative Maintenance Batteries Service | 69 | 22.0% | \$995.28 | \$68,674.32 |
| 13.0 | MEDSURG-PROCARE | PROCARE-SVC-MEDSURG-BEDS Parts, Labor, Travel Preventative Maintenance Batteries Service | 3 | 22.0% | \$995.28 | \$2,985.84 |
| 14.0 | SURFACES-PROCARE | PROCARE-SVC-BED-SURFACES Parts, Labor, Travel Preventative Maintenance Batteries Service | 12 | 22.0% | \$1,213.68 | \$14,564.16 |
| 15.0 | MEDSURG-PROCARE | PROCARE-SVC-MEDSURG-BEDS Parts, Labor, Travel Preventative Maintenance Batteries Service | 11 | 22.0% | \$995.28 | \$10,948.08 |
| 16.0 | ICU-BARI-PROCARE | PROCARE-SVC-ICU-BARI-LD-BEDS Parts, Labor, Travel Preventative Maintenance Batteries Service | 4 | 22.0% | \$2,336.88 | \$9,347.52 |
| 17.0 | MEDSURG-PROCARE | PROCARE-SVC-MEDSURG-BEDS Parts, Labor, Travel Preventative Maintenance Batteries Service | 2 | 22.0% | \$995.28 | \$1,990.56 |
| 18.0 | SURFACES-PROCARE | PROCARE-SVC-BED-SURFACES Parts, Labor, Travel Preventative Maintenance Batteries Service | 2 | 22.0% | \$1,213.68 | \$2,427.36 |
| 19.0 | MEDSURG-PROCARE | PROCARE-SVC-MEDSURG-BEDS Parts, Labor, Travel Preventative Maintenance Batteries Service | 2 | 22.0% | \$995.28 | \$1,990.56 |
| ProCare Total: | | | | | | \$404,879.28 |

Price Totals:

Pricing Per Vizient CE7563; terms and conditions per Cross-Divisional Product Pricing Agreement between the parties dated December 1, 2020.

Total will be billed annually: \$202,439.64 per year. See attachment 1 for equipment details including locations.

Authorized Customer Signer (Printed)

Date

Stryker Authorized Signature (Printed)

Date



1 Year Prevent

Quote Number:

10929738

Version:

1

Prepared For:

COUNTY OF VENTURA

Attn:

Rep:

Michele Marvin

Email:

michele.marvin@stryker.com

Phone Number:

GPO:

Vizient

Quote Date:

06/24/2024

Expiration Date:

09/28/2024

Contract Start:

07/25/2024

Contract End:

07/25/2026

Service Rep:

Quincy Jountti

Email:

quincy.jountti@stryker.com

Authorized Customer Signature

Date

Stryker Authorized Signature

Date

Equipment Service Plan

| Line Item # | Model | Serial # |
|-------------|--------------------------|---------------|
| 1.0 | PROCARE-SVC-BED-SURFACES | 15D0075 |
| 1.0 | PROCARE-SVC-BED-SURFACES | 15G0254 |
| 1.0 | PROCARE-SVC-BED-SURFACES | 15G0289 |
| 1.0 | PROCARE-SVC-BED-SURFACES | 16D0080 |
| 1.0 | PROCARE-SVC-BED-SURFACES | 16D0083 |
| 1.0 | PROCARE-SVC-BED-SURFACES | 16D0085 |
| 1.0 | PROCARE-SVC-BED-SURFACES | 16D0087 |
| 2.0 | PROCARE-SVC-BED-SURFACES | 16B01166 |
| 2.0 | PROCARE-SVC-BED-SURFACES | 16B01167 |
| 2.0 | PROCARE-SVC-BED-SURFACES | 16B01168 |
| 2.0 | PROCARE-SVC-BED-SURFACES | 16B01299 |
| 2.0 | PROCARE-SVC-BED-SURFACES | 16B01300 |
| 3.0 | PROCARE-SVC-BED-SURFACES | 2020018601123 |
| 3.0 | PROCARE-SVC-BED-SURFACES | 2020018601125 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16B00902 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16B00905 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16B00958 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16B01142 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16B01147 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16B01151 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16B01199 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16B01211 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16B01338 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16B01354 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16B01369 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01628 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01629 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01630 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01636 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01640 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01659 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01660 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01663 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01665 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01666 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01668 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01669 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01670 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01671 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01672 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01676 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01677 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01678 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01679 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01681 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01682 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01685 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01687 |

| | | |
|-----|--------------------------|---------------|
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01689 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01691 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01692 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01693 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01697 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16C01707 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16D01782 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16D01784 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16D01785 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16D01786 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16D01791 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16D01794 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16E01964 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16E01972 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16E01974 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16E01975 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16E01976 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16E01987 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16E01992 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16E01998 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16E02000 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16E02003 |
| 4.0 | PROCARE-SVC-BED-SURFACES | 16E02008 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401176 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401207 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401209 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401212 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401213 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401214 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401215 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401218 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401219 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401220 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401230 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401231 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401233 |
| 5.0 | PROCARE-SVC-BED-SURFACES | 2021017401234 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502756 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502757 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502758 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502759 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502760 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502761 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502762 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502763 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502764 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502765 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502766 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502767 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502768 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502769 |

| | | |
|-----|------------------------------|------------|
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502770 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502771 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502772 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502773 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502774 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502775 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502776 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502777 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502778 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS | 200502779 |
| 7.0 | PROCARE-SVC-BED-SURFACES | 1000023045 |
| 7.0 | PROCARE-SVC-BED-SURFACES | 1000023046 |
| 7.0 | PROCARE-SVC-BED-SURFACES | 1000023047 |
| 7.0 | PROCARE-SVC-BED-SURFACES | 1000023053 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1606042002 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1606042003 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1606042004 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1606042005 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1606042006 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1606042007 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1606042008 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1606042009 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1606042010 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1607040915 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1607040916 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000746 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000747 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000748 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000749 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000754 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000764 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000766 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000767 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000768 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000770 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000771 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000773 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000774 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000775 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000777 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000778 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000779 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000780 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000783 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000784 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000786 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000790 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000791 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000792 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000793 |
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000794 |

| | | |
|------|------------------------------|---------------|
| 9.0 | PROCARE-SVC-BED-SURFACES | 2972000795 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301810 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301814 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301830 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301831 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301832 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301833 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301835 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301836 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301837 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301838 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301839 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301840 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301841 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301842 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301843 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301844 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301845 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301846 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301847 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301848 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301849 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301850 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301852 |
| 10.0 | PROCARE-SVC-BED-SURFACES | 2020021301853 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U04830 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U05604 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U05762 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U08516 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61060 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61061 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61062 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61063 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61064 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61065 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61066 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61067 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61068 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61069 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61070 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61071 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61072 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61073 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61074 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61075 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61076 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61077 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61078 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61079 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61080 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61081 |

| | | |
|------|------------------------------|-----------|
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61082 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61083 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61084 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61085 |
| 11.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | U61086 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 150116198 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 150116199 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 150116200 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 150116208 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 150116230 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515810 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515811 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515812 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515813 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515814 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515815 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515816 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515817 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515818 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515819 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515820 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515821 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515822 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515823 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515824 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515825 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515826 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515827 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515828 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515829 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515830 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515831 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515832 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515833 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515834 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515835 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515836 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515837 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515838 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515839 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515840 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515841 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515842 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515843 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515844 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515845 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515846 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515847 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515848 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515849 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515850 |

| | | |
|------|------------------------------|---------------|
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515851 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515852 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515853 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515854 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160515855 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516220 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516221 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516222 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516223 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516224 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516225 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516226 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516227 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516228 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516229 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516230 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516231 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516232 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516233 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516234 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516235 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160516236 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS | 160915207 |
| 13.0 | PROCARE-SVC-MEDSURG-BEDS | R07917 |
| 13.0 | PROCARE-SVC-MEDSURG-BEDS | R07920 |
| 13.0 | PROCARE-SVC-MEDSURG-BEDS | R07921 |
| 14.0 | PROCARE-SVC-BED-SURFACES | 2022016100485 |
| 14.0 | PROCARE-SVC-BED-SURFACES | 2022016100486 |
| 14.0 | PROCARE-SVC-BED-SURFACES | 2022016100487 |
| 14.0 | PROCARE-SVC-BED-SURFACES | 2022016100488 |
| 14.0 | PROCARE-SVC-BED-SURFACES | 2022016100596 |
| 14.0 | PROCARE-SVC-BED-SURFACES | 2022016100597 |
| 14.0 | PROCARE-SVC-BED-SURFACES | 2022016100615 |
| 14.0 | PROCARE-SVC-BED-SURFACES | 2022016100616 |
| 14.0 | PROCARE-SVC-BED-SURFACES | 2022016100617 |
| 14.0 | PROCARE-SVC-BED-SURFACES | 2022016100622 |
| 14.0 | PROCARE-SVC-BED-SURFACES | 2022016100623 |
| 14.0 | PROCARE-SVC-BED-SURFACES | 2022016100624 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS | 2108002657 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS | 2109000092 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS | 2202001723 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS | 2202001730 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS | 2202001758 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS | 2202002008 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS | 2202002011 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS | 2202002014 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS | 2202002017 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS | 2202002019 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS | 2202002021 |
| 16.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1000027424 |
| 16.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1000027425 |

| | | |
|------|------------------------------|---------------|
| 16.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1000027426 |
| 16.0 | PROCARE-SVC-ICU-BARI-LD-BEDS | 1000027427 |
| 17.0 | PROCARE-SVC-MEDSURG-BEDS | 2206000515 |
| 17.0 | PROCARE-SVC-MEDSURG-BEDS | 2206000516 |
| 18.0 | PROCARE-SVC-BED-SURFACES | 2021023301284 |
| 18.0 | PROCARE-SVC-BED-SURFACES | 2021023301412 |
| 19.0 | PROCARE-SVC-MEDSURG-BEDS | 2206000547 |
| 19.0 | PROCARE-SVC-MEDSURG-BEDS | 2206000548 |

Purchase Order Form



Account Manager _____
Cell Phone _____

Purchase Order Date _____
Expected Delivery Date _____
Stryker Quote Number _____

Check box if Billing same as Shipping ☐

| BILL TO | | CUSTOMER # |
|-----------------------|--|------------|
| Billing Account Num | | |
| Company Name | | |
| Contact or Department | | |
| Street Address | | |
| Addt'l Address Line | | |
| City, ST ZIP | | |
| Phone | | |

| SHIP TO | | CUSTOMER # |
|-----------------------|--|------------|
| Shipping Account Num | | |
| Company Name | | |
| Contact or Department | | |
| Street Address | | |
| Addt'l Address Line | | |
| City, ST ZIP | | |
| Phone | | |

Authorized Customer Initials _____

Authorized Customer Initials _____

| DESCRIPTION | QTY | TOTAL |
|--------------------------------------|----------------------|----------------------|
| REFERENCE QUOTE <input type="text"/> | <input type="text"/> | <input type="text"/> |

Accounts Payable Contact Information

Name _____
Email _____
Phone _____

Stryker Terms and Conditions
<https://techweb.stryker.com>

Authorized Customer Signature

Printed Name _____
Title _____
Signature _____
Date _____

Attachment Stryker Quote Number

*Sales or use taxes on domestic (USA) deliveries will be invoiced in addition to the price of the goods and services on the Stryker Quote.

Items located at SPH

Equipment Service Plan

| Line Item # | Model | Serial # |
|-------------|--|---------------|
| 1.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACE | 15D0075 |
| 1.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACE | 15G0254 |
| 1.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACE | 15G0289 |
| 1.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACE | 16D0080 |
| 1.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACE | 16D0083 |
| 1.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACE | 16D0085 |
| 1.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACE | 16D0087 |
| 2.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACE | 16B01166 |
| 2.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACES | 16B01167 |
| 2.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACE | 16B01168 |
| 2.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACE | 16B01299 |
| 2.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACE | 16B01300 |
| 3.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACE | 2020018601123 |
| 3.0 | PROCARE-SVC-BED-SURFACES ISOAIR, DOMESTIC POWER SURFACE | 2020018601125 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16B00902 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16B00905 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16B00958 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16B01142 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16B01147 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16B01151 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16B01199 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16B01211 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16B01338 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16B01354 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16B01369 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01628 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01629 |
| 4.0 | PPRO CARE-SVC-BED-SURFACES SYK AIR PMP | 16C01630 |
| 4.0 | PPRO CARE-SVC-BED-SURFACES SYK AIR PMP | 16C01636 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01640 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01659 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01660 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01663 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01665 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01666 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01668 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01669 |
| 4.0 | PPRO CARE-SVC-BED-SURFACES SYK AIR PMP | 16C01670 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01671 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01672 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01676 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01677 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01678 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01679 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01681 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01682 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01685 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01687 |

| | | |
|-----|--|---------------|
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01689 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01691 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01692 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01693 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01697 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16C01707 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16D01782 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16D01784 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16D01785 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16D01786 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16D01791 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16D01794 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16E01964 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16E01972 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16E01974 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16E01975 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16E01976 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16E01987 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16E01992 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16E01998 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16E02000 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16E02003 |
| 4.0 | PROCARE-SVC-BED-SURFACES SYK AIR PMP | 16E02008 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401176 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401207 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401209 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401212 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401213 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401214 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401215 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401218 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401219 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401220 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401230 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401231 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401233 |
| 5.0 | PROCARE-SVC-BED-SURFACES ISO TOUR PUMP | 2021017401234 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502756 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502757 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502758 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502759 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502760 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502761 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502762 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502763 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502764 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502765 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502766 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502767 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502768 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502769 |

| | | |
|-----|--|------------|
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502770 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502771 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502772 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502773 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502774 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502775 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502776 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502777 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502778 |
| 6.0 | PROCARE-SVC-MEDSURG-BEDS S3 PX2-3005 | 200502779 |
| 7.0 | PROCARE-SVC-BED-SURFACES S3 PX2-3005 | 1000023045 |
| 7.0 | PROCARE-SVC-BED-SURFACES S3 PX2-3005 | 1000023046 |
| 7.0 | PROCARE-SVC-BED-SURFACES S3 PX2-3005 | 1000023047 |
| 7.0 | PROCARE-SVC-BED-SURFACES S3 PX2-3005 | 1000023053 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS LD304 MATERNITY BED | 1606042002 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS LD304 MATERNITY BED | 1606042003 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS LD304 MATERNITY BED | 1606042004 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS LD304 MATERNITY BED | 1606042005 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS LD304 MATERNITY BED | 1606042006 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS LD304 MATERNITY BED | 1606042007 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS LD304 MATERNITY BED | 1606042008 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS LD304 MATERNITY BED | 1606042009 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS LD304 MATERNITY BED | 1606042010 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS LD304 MATERNITY BED | 1607040915 |
| 8.0 | PROCARE-SVC-ICU-BARI-LD-BEDS LD304 MATERNITY BED | 1607040916 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000746 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000747 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000748 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000749 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000754 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000764 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000766 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000767 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000768 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000770 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000771 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000773 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000774 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000775 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000777 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000778 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000779 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000780 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000783 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000784 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000786 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000790 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000791 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000792 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000793 |
| 9.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2972000794 |

| | | |
|------|---------------------------------------|---------------|
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160515851 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160515852 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160515853 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160515854 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160515855 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516220 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516221 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516222 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516223 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516224 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516225 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516226 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516227 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516228 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516229 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516230 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516231 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516232 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516233 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516234 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516235 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160516236 |
| 12.0 | PROCARE-SVC-MEDSURG-BEDS S3 EX - 3005 | 160915207 |
| 13.0 | PROCARE-SVC-MEDSURG- GoBed II | R07917 |
| 13.0 | PROCARE-SVC-MEDSURG- GoBed II | R07920 |
| 13.0 | PROCARE-SVC-MEDSURG- GoBed II | R07921 |
| 14.0 | PROCARE-SVC-BED-SURFACES ISOTOUR | 2022016100485 |
| 14.0 | PROCARE-SVC-BED-SURFACES ISOTOUR | 2022016100486 |
| 14.0 | PROCARE-SVC-BED-SURFACES ISOTOUR | 2022016100487 |
| 14.0 | PROCARE-SVC-BED-SURFACES ISOTOUR | 2022016100488 |
| 14.0 | PROCARE-SVC-BED-SURFACES ISOTOUR | 2022016100596 |
| 14.0 | PROCARE-SVC-BED-SURFACES ISOTOUR | 2022016100597 |
| 14.0 | PROCARE-SVC-BED-SURFACES ISOTOUR | 2022016100615 |
| 14.0 | PROCARE-SVC-BED-SURFACES ISOTOUR | 2022016100616 |
| 14.0 | PROCARE-SVC-BED-SURFACES ISOTOUR | 2022016100617 |
| 14.0 | PROCARE-SVC-BED-SURFACES ISOTOUR | 2022016100622 |
| 14.0 | PROCARE-SVC-BED-SURFACES ISOTOUR | 2022016100623 |
| 14.0 | PROCARE-SVC-BED-SURFACES ISOTOUR | 2022016100624 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY | 2108002657 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY | 2109000092 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY | 2202001723 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY | 2202001730 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY | 2202001758 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY | 2202002008 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY | 2202002011 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY | 2202002014 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY | 2202002017 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY | 2202002019 |
| 15.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY | 2202002021 |
| 16.0 | PROCARE-SVC-ICU-BARI-LD-BEDS BARI10A | 1000027424 |
| 16.0 | PROCARE-SVC-ICU-BARI-LD-BEDS BARI10A | 1000027425 |

| | | |
|------|--|---------------|
| 16.0 | PROCARE-SVC-ICU-BARI-LD-BEDS BARI10A | 1000027426 |
| 16.0 | PROCARE-SVC-ICU-BARI-LD-BEDS BARI10A | 1000027427 |
| 17.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY ZX WITH ISOTOUR | 2206000515 |
| 17.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY ZX WITH ISOTOUR | 2206000516 |
| 18.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2021023301284 |
| 18.0 | PROCARE-SVC-BED-SURFACES ISOLIBRIUM | 2021023301412 |
| 19.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY ZX WITH ISOAIR | 2206000547 |
| 19.0 | PROCARE-SVC-MEDSURG-BEDS PROCUIITY ZX WITH ISOAIR | 2206000548 |