

Hazardous Materials Discharge Summary Report

This Summary Report is a list of all reports of incidents received from
09/25/2021 through 10/01/2021

<i>Date of Incident</i>	<i>Location</i>	<i>Material</i>	<i>Estimated Amount</i>
9/29/2021 <i>Rpt#:</i> 102302 <i>Description:</i> AN ELECTRICAL CONTRACTOR WAS EXCAVATING AND STRUCK A 1" STEEL GAS LINE CAUSING THE RELEASE.	8988 N VENTURA AVE VENTURA	NATURAL GAS	UNKNOWN
9/29/2021 <i>Rpt#:</i> 102303 <i>Description:</i> A GAS STATION CUSTOMER WAS REFUELING THEIR VEHICLE AND SPILLED THE DIESEL ON THE PAD.	920 S SEAWARD AVE VENTURA	DIESEL	3 GALLON(S)
9/30/2021 <i>Rpt#:</i> 102304 <i>Description:</i> TRANSFORMER HAD MECHANICAL FAILURE WHICH CAUSED THE RELEASE OF THE MATERIAL ONTO DRIVEWAY THEN INTO THE GUTTER.	111 NORTH 8TH ST SANTA PAULA	TRANSFORMER OIL	3 GALLON(S)
9/30/2021 <i>Rpt#:</i> 102305 <i>Description:</i> SEWER LINE BLOCKAGE CAUSED THE SPILL.	729 LOMA VISTA RD VENTURA	SEWAGE	25 GALLON(S)

The locations of these releases are given by post office address whenever possible. These addresses include city name, however, no determination as to the location of the release relative to the corporate boundaries of any city is intended.