

Hazardous Materials Discharge Summary Report

This Summary Report is a list of all reports of incidents received from
10/5/24 through 10/11/24

Date of Incident	Location	Material	Estimated Amount
10/5/2024 <i>Rpt#:</i> 102846	607 N. M STREET OXNARD	SEWAGE	140 GALLON(S)
<i>Description:</i> Main sewer line clogged with gravel causing release.			
10/8/2024 <i>Rpt#:</i> 102848	LYNWOOD DRIVE CAMARILLO	MOTOR OIL	0.5 GALLON(S)
<i>Description:</i> Oil substance reported on street from vehicle motor oil pan.			

The locations of these releases are given by post office address whenever possible. These addresses include city name, however, no determination as to the location of the release relative to the corporate boundaries of any city is intended.
