Hazardous Materials Discharge Summary Report

This Summary Report is a list of all reports of incidents received from 06/29/2019 through 07/05/2019

Date of Incident	Location	Material	Estimated Amount
6/29/2019 Rpt#: 101898	101 WEST ESPLANADE OXNARD	DIESEL	5 GALLON(S)
	CKET OF DIESEL FELL FROM THE BACK OF A JCK AND SPILLED ONTO THE ROADWAY.		
7/2/2019	BETWEEN PORT HUENEME AND ANACAPA	PETROLEUM	150 GALLON(S)
Rpt#: 101900 Description: 50 F CAU	PORT HUENEME FOOT VESSEL SANK DUE TO AN UNKNOWN JSE.		
7/5/2019 Rpt#: 101899	3048 SOLIMAR BEACH DRIVE VENTURA	SEWAGE	65 GALLON(S)
	CHARGE WAS THE RESULT OF A FAILING STEWATER COLLECTION SYSTEM.		

The locations of these releases are given by post office address whenever possible. These addresses include city name, however, no determination as to the location of the release relative to the corporate boundaries of any city is intended.