## Hazardous Materials Discharge Summary Report

## This Summary Report is a list of all reports of incidents received from 03/02/2019 through 03/08/2019

Date of			
Incident	Location	Material	Estimated Amount
03/03/2019 <i>Rpt</i> #: 101828	SURFER'S KNOLL, VENTURA VENTURA	TAR CLUMPS	UNKNOWN
	very of large amount of tar clumps washing up on the from an unknown source.		
03/05/2019 Rpt#: 101829	6885 COYOTE RD, SOUTH MOUNTAIN OILFIELD, COLBERT TANK SETTING SOMIS	OIL - CRUDE TYPE	18 BARREL(S)
	g line possibly ruptured for unknown reason, which d the release onto soil.		
03/05/2019 <i>Rpt#</i> : 101830	250 DOVE CT, SANTA PAULA 93060 SANTA PAULA	RAW SEWAGE	1500 GALLON(S)
Description: Sewage coming out of a manhole contained to paved lot and private storm drain.			
03/05/2019	1607 LOS ANGELES AVE UNIT 1, VENTURA 93004	LATEX PAINT	5 GALLON(S)
Rpt#: 101831	VENTURA		
Description: Latex paint was spilled in a work truck bed and the truck was washed off onto the road.			
03/08/2019	33 FREEWAY AT CANADA LARGA	DEGREASER AND VEGETABLE OIL MIXED WITH WATER	40 GALLON(S)
Rpt#: 101832	VENTURA		
release	aser and vegetable oil mixed with water was ed onto the roadway and into the Canada Larga from a chemical facility.		

The locations of these releases are given by post office address whenever possible. These addresses include city name, however, no determination as to the location of the release relative to the corporate boundaries of any city is intended.