

## **EXHIBIT 6**

## Wildlife Crossing Structure Detail Maps Located on Gridley Road

Proposed Ordinance Establishing Setbacks from 16 Wildlife Crossing Structures in the Northern Portion of the Ventura County Unincorporated Area











Ventura County Culvert ID: 69112-1-1 & ~ 200 Foot Setback Area

Disclaimer: this map was created by the Ventura County Resource Management Agency Information Systems GIS, which is designed and operated solely for the convenience of the County and related public agencies. The County does not warrant the accuracy of this map and no decision involving a risk of economic loss or physical injury should be made in reliance therein

